

COBONE



XJ-30
磁吸支架说明书

○ 部件名称



○ 规格参数

Model	Material	Screw	Diameter	Storage	Highest	Minimum	Bearing	Weight
XJ-30	铝合金	1/4"螺孔	16mm	155mm	/	800g	72g	

*为了改善产品, 有设计/规格/参数的变动时以实物为准

○ 产品展示



○ 包转清单

- 1.XJ-30磁吸支架
- 2.合格证
- 3.保修卡
- 4.六角扳手
- 5.包装盒

○ 注意事项


- 1.请在使用前, 务必仔细了解并掌握产品功能、使用技巧和有关注意事项。
- 2.不要超过支撑设备最大标称负重及最大建议负重使用(请参考具体产品介绍)。
- 3.请勿在低于零下15摄氏度及高于70摄氏度的温度下操作。
- 4.当使用产品时, 请经常检查各锁紧机构及装置。
- 5.当在潮湿、沙地、尘埃的环境下使用产品后, 请及时将产品擦干及清洁。请勿在海水、酸雨及腐蚀性环境中使用。
- 6.在移动和运输过程中, 务必将相机和镜头移除。
- 7.请定期检查支撑设备, 及早发现可能出现的磨损、故障或损坏。
- 8.切勿自行添加和擦拭任何润滑油。如确实需要时, 请联系客服人员

COBONE



XJ-30
Magnetic support bracket

○ Component Name



Model	Material	Screw	Diameter	Storage	Highest	Minimum	Bearing	Weight
XJ-30	Aluminum	1/4" Screw	16mm	155mm	/	800g	72g	

*In order to improve the product, any changes in design/ specifications/ parameters shall be based on the actual product.

○ Product display



○ Packaging List

- 1.XJ-30magnetic holder
- 2.certificate
- 3.Warranty card
- 4.Hexagonal wrench
- 5.Packaging box

○ Attention Notes

- 1.Please carefully understand and master the product features, usage techniques and related precautions before use.
- 2.Do not exceed the marked/recommended maximum load weight (Please refer to the specific product introduction).
- 3.Do not operate at temperatures below minus 15 degrees Celsius and above 70 degrees Celsius.
- 4.When using the product, please regularly check all locking mechanisms and devices.
- 5.After using the product in wet, sandy, or dusty environments please dry and clean it at the first time.Keep away from seawater, acid rain, or corrosive environments
6. During movement and transportation, please remove the equipment.
- 7.Do not add or wipe any lubricating oil by yourself. If necessary, please contact our customer service personnel.